Feceived at: 10:09AM, 3/26/2002

26. MAR. 2002 15:49

Wb +498954301/00

1.0089108910891088 NK. 1426 S. 28/49

OBLON ET AL (703) 413-3000 DOCKET # 22 141405 SHEET 1 OF 6

PCT/EP00/10518

WO 01/33530

1/6 सं

[1

26. MAK. 2002 15:49

10069089.10/089088


NK. 1426 S. 29/49

L +498954301700

PCT/EP00/10518

WO 01/33530

OBLON ET AL (703) 413-3000 DOCKET #221414USHEET 2-OF 6



(5...)

26. MAK. 2002 15:49

₩

+498954301/00

10/089088


NK. 1426 S. 30/49

WO 01/33530

PCT/EP00/10518

OBLON ET AL (703) 413-3000

DOCKET # 221414 U S SHEET 3 OF 6



Received at: 10:09AM, 3/26/2002

26. MAR. 2002 15:49

WBEIAL +498954301/00

NK. 1426 S. 31/49

PCT/EP00/10518

WO 01/33530

OBLON ET AL (703) 413-3000

DOCKET #221414 US SHEET 4 OF 6

4/6 8 Data transmitter 6A Vehicle-information device 4 receiver GPS

Received at: 10:09AM, 3/26/2002

- 26. MAR. 2002 15:50

ز ي:

WB +498954301/00

NK. 1426 S. 32/49

PCT/EP00/10518

WO 01/33530

OBLON ET AL (703) 413-3000 DOCKET # 221414 US SHEET 5 OF 6

5/6 Wehicle-information device 4 Direction-finding transmitter

<u>.</u>

26. MAR. 2002 15:50

WB +498954301/00

NK. 1426 S. 33/49

WO 01/33530

OBLON ET AL (703) 413-3000 DOCKET #221414 USSHEET 6 OF 6 PCT/EP00/10518

